

=DO NOT SCALE DRAWING=

PIVOT MOUNTING INSTRUCTIONS  
THRESHOLD PORTION OF PIVOT

<p>1.</p> <p>PIVOT BASE</p> <p>MOUNTING STUD SCREW PIVOT BASE ON MTG. STUD UNTIL FINGER TIGHT.</p>	<p>2.</p> <p>FLUSH</p> <p>SCREW DOWN PIVOT BASE ASSEMBLY TO THRESHOLD, UNTIL MOUNTING STUD IS FLUSH AS SHOWN.</p>
<p>3.</p> <p>1/2-13 JAMB NUT</p> <p><u>IMPORTANT:</u> TO PREVENT STRIPPING, HOLD MTG. STUD WITH SCREW DRIVER WHILE TIGHTENING JAMB NUT.</p>	<p>4.</p> <p>SCREW DOWN PIVOT BASE TO DESIRED HEIGHT. ADJUST AS REQUIRED.</p>

USAGE: 21-101-AE,EF,BV,UP TYP. KITS

DIMENSIONAL TOLERANCES UNLESS OTHERWISE SPECIFIED		APPROVALS	DATE
DECIMAL DIMENSIONS .XX	± .010	APPROVED	
DECIMAL DIMENSIONS .XXX	± .005	CHECKED	
ANGULAR ± °	FRACTIONAL ± 1/64	DRAWN	R.M. 4.24.04
MATERIAL		SCALE	NONE

FILE NO.	FINISH
NEXT ASSY.	HEAT TREAT
QTY. USED	

INST. INSTR. C-HUNG  
20-647,20-607 PORTIONS

**jackson**  
CORPORATION

3447 UNION PACIFIC AVE.  
LOS ANGELES, CALIF. 90023

SHEET 1 OF 1 SHEETS	
DWG. NO.	REV.
10-272	A