



(-) BLACK TO
 (+) RED TO
 POWER SUPPLY
 24VDC
 (500ma MAX.)

CLOSER CONTROL BOARD

OFF ←
 1
 2
 3
 4
 TIMER CONTROL

1 2 3 4 5 6 7 8 9 10 11 12

GREEN
 BLACK
 RED

ON/OFF SWITCH

PUSH BUTTON

MOTOR MUST TURN CW WHEN
 HOOKING WIRES FROM MOTOR
 TO 1 & 2 TERMINALS

POWER ASSISTED ASS'Y

POWER SUPPLY

PUSH BUTTON

| | | | |
|---------------------------------------------------|-------------------|-----------|------------|
| DIMENSIONAL TOLERANCES UNLESS OTHERWISE SPECIFIED | | APPROVALS | DATE |
| DECIMAL DIMENSIONS .XX ± .010 | | APPROVED | |
| DECIMAL DIMENSIONS .XXX ± .005 | | CHECKED | |
| ANGULAR ± ° | FRACTIONAL ± 1/64 | DRAWN | RM 8.15.06 |

| | |
|------------|------------|
| FILE NO. | MATERIAL |
| NEXT ASSY. | FINISH |
| QTY. USED | HEAT TREAT |

SHEET 1 OF 1 SHEETS
 SCHEMATIC PWR ASSIST
 O.H.C. MECH.

jackson
 CORPORATION®
 3447 UNION PACIFIC AVE.
 LOS ANGELES, CALIF. 90023

| | |
|---------------------|------|
| SHEET 1 OF 1 SHEETS | |
| DWG. NO. | REV. |
| 10-1131 | 3 |